Owner Name and Address: White Enterprises 7505 MT Highway 35 Bigfork MT 59911 Phone: (406) 837-6170

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1502482	Your Turn Convenience Stop	7505 MT Highway 35	Bigfork	59911	(406) 837-6170

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / 06 Currently In Use	3185	1/10/1997 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
7 / 07 Currently In Use	3186	1/10/1997 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGHIJKU (D) EFGHIJKU	Yes Yes Yes Yes
8 / 08 Currently In Use	3187	1/10/1997 09 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJ&L ● ●EFGHIJ&L</pre>	Yes Yes Yes Yes
9 / 09 Currently In Use	3188	11/1/1997 08 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJKL ● ●EFGHIJKL</pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 99

Owner Name and Address: Marina Cay Resort PO Box 663 Bigfork MT 59911 Phone: (406) 837-5861

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1503002	Marina Cay Resort	180 Vista Dr	Bigfork	59911	(406) 837-5861

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently In Use	4067 5	5/5/1999 07 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABC) € F G H () (R L) (B) € F O H () (R L)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 99

Owner Name and Address: Flathead Lake Lodge PO Box 248 Bigfork MT 59911 Phone: (406) 837-3815

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1504551	Flathead Lake Lodge	150 Flathead Lake Lodge Road	Bigfork	59911	(406) 837-4391	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 04 Currently in Use	1826	5/14/1992 14 / No	Gasoline 1,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	B D E F G H I J K L	Yes Yes Yes Yes
2 / 05 Currently in Use	1827	6/1/1994 12 / No	Gasoline 600	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	B DEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

Owner Name and Address: Local Joes Gas & Grub LLC 8089 Highway 35 PO Box 2375 Bigfork MT 59911 Phone: (406) 837-5580

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1506086	Local Joes Gas & Grub LLC	8089 MT Highway 35	Bigfork	59911	(406) 837-5580

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / 06 Currently in Use	2283	10/1/1991 14 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJ&L ● ●EFGHIJ&L</pre>	Yes Yes Yes Yes
7 / 07 Currently in Use	2284	10/1/1991 14 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGH() (K)	Yes Yes Yes Yes
8 / 08 Currently in Use	2285	10/1/1991 14 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJ&L ● ●EFGHIJ&L</pre>	Yes Yes Yes Yes
9 / 09 Currently in Use	2286	3/1/1994 12 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJKL ● ●EFGHIJKL</pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

Owner Name and Address: Kleivland Inc PO Box 1426 Bigfork MT 59911 Phone: (406) 837-5597

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1507199	Ferndale Market	1845 MT Highway 209	Bigfork	59911	(406) 837-5597

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3254	4/28/1976 30 / No	Diesel 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Pressurized	(ABCOEFGHIJKL) (BCOEFGHIJKL)	Yes Yes Yes Yes
2 / 02 Currently in Use	3255	4/28/1977 29 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Pressurized		Yes Yes Yes Yes
3 / 03 Currently in Use	3256	6/1/1993 13 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH))(KU (OBFGH))(KU	Yes Yes Yes Yes
4 / 04 Currently in Use	3257	6/1/1993 13 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH)J&L (OBFGH)J&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 99

Owner Name and Address: Forkins Echo Lake Store 110 Swan River Road Bigfork MT 59911 Phone: (406) 249-9043

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1507361	Echo Lake Store	110 Swan River Road	Bigfork	59911	(406) 837-4727

TankiD/Alt TankiD Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / 06 Currently in Use	3498	11/1/1995 10 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABCOEFGH) (KL) (B DEFGH) (KL)	Yes Yes Yes Yes
7 / 07 Currently in Use	3499	11/1/1995 10 / No	Gasoline 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • E F G H J J K L B D E F G H J • K L	Yes Yes Yes Yes
8 / 08 Currently in Use	3500	11/1/1995 10 / No	Diesel 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABC•EFGH1J&L B DEFGH1•&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 99

Owner Name and Address: Old Town Center LLC PO Box 2497 Bigfork MT 59911 Phone: (406) 837-5029

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1509801	Big Fork Sinclair Express Pay	8111 MT Highway 35	Bigfork	59911	(406) 837-5029

TankiD/Alt TankiD Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	481	5/1/1981 25 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Safe Suction	B D E F G H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	482	5/1/1981 25 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Safe Suction	(A) B) (C) (E) (F) (G) (H) (J) (K) (L) (B) (D) (F) (G) (H) (J) (K) (L)	Yes Yes Yes Yes
3 / 03 Currently in Use	483	7/1/1993 13 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(A B C • E F G H) J (K L) (B D E F G H) • (K L)	Yes Yes Yes Yes
4 / 04 Currently in Use	484	4/1/1995 11 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC • EFGH) J (K L) (B	Yes Yes Yes Yes
5 / 05 Currently in Use	485	4/1/1995 11 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • E F G H 1 J K L B D E F G H 1 • K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 7 of 99

Rocky Mountain Recreational Communities LLC Owner Name and Address: 301 Eagle Bend Dr Bigfork MT 59911 Phone: (406) 837-0711

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
,	Location Name	Location Street Address	Location City	Zip	Location Phone
1513152	Eagle Bend Yacht Harbor	371 Eagle Bend Dr	Bigfork	59911	(406) 837-0711

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	4013	7/1/1993 13 / No	Gasoline 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCDEF.HIJKL B DEF.HIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	4014	7/1/1993 13 / No	Diesel 1,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCDEF.H).(KL) (B DEF.H).(KL)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 8 of 99

Owner Name and Address: Moon Rise at Yellow Bay Inc 17998 E Shore Route Bigfork MT 59911 Phone: (406) 982-3569

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2404016	Moon Rise at Yellow Bay Inc	17998 E Shore Route	Bigfork	59911	(406) 982-3569

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Temporarily Out of Us		11/1/1994 11 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	B DEFGHIJKL B DEFGHIØKL	Yes Yes Yes Yes
4 / 04 Temporarily Out of Us		11/1/1994 11 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(A • • D E F G H) J K L B D E F G H) • K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 9 of 99

Owner Name and Address: Swan Lake Stage Stop Inc 72241 Mt Highway 83 Bigfork MT 59911 Phone: (406) 886-2300

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2405644	Swan Lake Stage Stop Inc	72241 MT Highway 83	Bigfork	59911	(406) 886-2300

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 04 Currently in Use	3325	5/7/1986 20 / No	Gasoline 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL (OBEFGHIJKL)	Yes Yes Yes Yes
2 / 05 Currently in Use	3326	5/7/1986 20 / No	Gasoline 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGH() (K) (D) (D) (EFGH() (K)	Yes Yes Yes Yes
3 / 06 Currently in Use	3327	7/1/1996 10 / No	Diesel 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGH (J) (K) (L) (D) (B) (B) (B) (B) (B) (B) (B) (B) (B) (B	Yes Yes Yes Yes
4 / 07 Currently in Use	3328	7/1/1996 10 / No	Diesel 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGH() (KL) (D) (B) (B) (B) (B) (B) (B) (B) (B) (B) (B	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 10 of 99

Owner Name and Address: WWW Woods Bay Inc 26787 E Shore Route Highway 35 PO Box 8093 Bigfork MT 59911 Phone: (406) 837-4

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2406085	Bobs Woods Bay Market	26787 E Shore Route	Bigfork	59911	(406) 837-4884

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	1279	1/30/1984 22 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Not Listed	ABC • E F G H 1 J K L • • E F G H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	1280	1/30/1984 22 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Not Listed	(ABCOEFGH)JKL (DEFGH)JKL	Yes Yes Yes Yes
3 / 03 Currently in Use	1281	5/1/1994 12 / No	Diesel 4,000	STI-P3 Impressed Current	Bare Steel Impressed Current	Safe Suction	(ABCOEFGH)JKL B DEFGH)OKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 11 of 99

Owner Name and Address: Bigfork Stage Stop Inc 8263 MT Highway 35 Bigfork MT 59911 Phone: (406) 837-5858

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613885	Bigfork Stage Stop Inc	8263 MT Highway 35	Bigfork	59911	(406) 837-1551

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	3531	10/1/1998 07 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H J K L B D E F • H J K L	Yes Yes Yes Yes
2 / 02 Currently In Use	3532	10/1/1998 07 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH)JKL (B DEFOH)JKL	Yes Yes Yes Yes
3 / 03 Currently In Use	3533	10/1/1998 07 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 99

Owner Name and Address: Roe Hatlen PO Box 3062 Kalispell MT 59903 Phone: (406) 885-3160

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614137	Roe Hatlen	21143 E Shore Route	Bigfork	59911	(406) 885-3160

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	5024	3/21/2005 01 / No	Gasoline 1,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABC) € F G H () (R) (B) € F O H () (R)	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 13 of 99

Owner Name and Address: The Owens Co 111 River Butte Dr Columbia Falls MT 59912 Phone: (406) 892-4646

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1501675	North Fork Store	673 8th Avenue East N	 Columbia Falls	59912	(406) 892-4646	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3522	4/23/1969 37 / No	Gasoline 5,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<pre></pre>	Yes Yes Yes Yes
2 / 02 Currently in Use	3523	4/23/1969 37 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJK)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 14 of 99

Owner Name and Address: David & Sharon Brotnov PO Box 1407 Columbia Falls MT 59912 Phone: (406) 892-2004

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1502820	D & S Junction	7322 US Highway 2 E	Columbia Falls	59912	(406) 892-2004

TankID/Alt TankID Status	Tag Installe Numbe Age/AS		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	496 7/1/1977 29 / N	Gasoline 0 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	497 7/1/1977 29 / N	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Double-Walled	Pressurized	8 0 E F 6 H 1 J K L	Yes Yes Yes Yes
3 / 03 Currently in Use	498 7/1/1977 29 / N	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	499 11/17/198 17 / N	0.000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic Double-Walled	Pressurized	A • C • E F G H I J K L • • E F G H I J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 15 of 99

Owner Name and Address: Columbia Falls Aluminum Co LLC 2000 Aluminum Dr Columbia Falls MT 59912 Phone: (406) 892-8400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1504003	Columbia Falls Aluminum Co LLC	2000 Aluminum Dr	Columbia Falls	59912	(406) 892-3261

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / 16W Currently in Use	3413	7/18/1989 16 / No	Diesel 12,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic Secondary Containment	Pressurized	ABCDEF•HIJKL B •EFGHIJKL	Yes Yes Yes Yes
9 / 18W Currently in Use	3415	7/18/1989 16 / No	Diesel 3,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic Secondary Containment	Pressurized	B © E F G H 1 J K L	Yes Yes Yes Yes
10 / 17W Currently in Use	3414	7/18/1989 16 / No	Gasoline 5,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic Secondary Containment	Pressurized	ABCDEF.H.J.K.L B.EFGH.J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 16 of 99

Owner Name and Address: Mikes of Columbia Falls Inc 1645 9th St W Columbia Falls MT 59912 Phone: (406) 892-2078

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone]
1506839	Mikes Conoco Columbia Falls	1695 US Highway 2 W	Columbia Falls	59912	(406) 892-2078	•

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 05 Currently in Use	4466	7/1/1996 10 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Secondary Containment	Pressurized	B DEFG . J J & L	Yes Yes Yes Yes
3 / 06 Currently in Use	3366	7/1/1996 10 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Secondary Containment	Pressurized	B DEFG 1 1 K L	Yes Yes Yes Yes
4 / 07 Currently in Use	3367	7/1/1996 10 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Secondary Containment	Pressurized	(ABC • EF G + 1) & L B D EF G • 1) & L	Yes Yes Yes Yes
5 / 08 Currently in Use	3368	7/1/1996 10 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Secondary Containment	Pressurized	(ABC • EF G + 1) (K L) (B D EF G • 1) (K L)	Yes Yes Yes Yes
6 / 09 Currently in Use	3369	7/1/1996 10 / No	Diesel 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Secondary Containment	Pressurized	ABC • E F G H J K L B D E F G • J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 17 of 99

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1508690	Town Pump Inc Columbia Falls 1	502 9th St W	Columbia Falls	59912	(406) 892-2245

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	2420	7/14/1981 24 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(A	Yes Yes Yes Yes
5 / 05 Currently in Use	4380	10/1/1985 20 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
6 / 06 Currently in Use	4381	7/14/1989 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH)J&L (OBFGH)J&L	Yes Yes Yes Yes
7 / 07 Currently in Use	2423	7/14/1989 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH)JKL • • EFGH)JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 18 of 99

Owner Name and Address: Arends Gas and Cast 7358 Highway 2 East Columbia Falls MT 59912 Phone: (406) 892-2097

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1511333	Arends Gas and Cast	7356 US Highway 2 E	Columbia Falls	59912	(406) 892-4835

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	686	1/1/1990 16 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	U.S. Suction	ABC • E F G H 1 J K L B • E F G H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	687	1/1/1990 16 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	U.S. Suction	B	Yes Yes Yes Yes
3 / 03 Currently in Use	688	1/1/1990 16 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	U.S. Suction	(A B C • E F G H) J (K L) (B • E F G H) J (K L)	Yes Yes Yes Yes
4 / 04 Currently in Use	689	1/1/1990 16 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	U.S. Suction	(ABCOEFGH)J&L (BOEFGH)J&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 19 of 99

Owner Name and Address: Camas Pack LLC 9293 West Road Cleves OH 45002 Phone: (513) 505-5716

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1512800	Home Ranch Store	8855 N Fork Road	Columbia Falls	59912	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Temporarily Out of U		6/1/1992 14 / No	Gasoline 2,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Safe Suction	ABCOEFGHIJKU B DEFGHIJKO	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 20 of 99

Owner Name and Address: Valcon Distributing LTD PO Box 9200 Kalispell MT 59904 Phone: (406) 755-6611

Sys Fac I	Location Name	Location Street Address	Locati	on City Zip	Location Phone	
1512972	Valcon Distributing Columbia Falls Truck	195 Truck Route Road	Colum	bia Falls 59912	(406) 755-6611	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01	4404 12/15/1992	Diesel	STI-P3	Flexible Plastic	Pressurized	ABC ● EFGH1JKL	Yes
Currently in Use	13 / No	15,000	None	Double-Walled		B DEF●H1●KL	Yes Yes Yes
2 / 04 Currently in Use	4405 11/15/1992 13 / No	Gasoline 5,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	B DEF G H 1 O K L	Yes Yes Yes Yes
3 / 05	4406 11/15/1992	Gasoline	STI-P3	Flexible Plastic	Pressurized	ABC●EFGH () &L	Yes
Currently in Use	13 / No	5,000	None	Double-Walled		B DEF●H () ●&L	Yes Yes Yes
4 / 03	4407 11/15/1992	Diesel	STI-P3	Flexible Plastic	Pressurized	ABC●EFGH () &L	Yes
Currently in Use	13 / No	8,000	None	Double-Walled		B DEF●H () ●&L	Yes Yes Yes
5 / 02	4408 11/15/1992	Gasoline	STI-P3	Flexible Plastic	Pressurized	ABCOEFGHIJKL	Yes
Currently in Use	13 / No	10,000	None	Double-Walled		B DEFOHIOKL	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 21 of 99

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5613825	Town Pump Inc Columbia Falls 2	6106 US Highway 2 W	Columbia Falls	59912	(406) 892-0747	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	2674	10/1/1997 08 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B DEF H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently In Use	4670	10/1/1997 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B DEF H J K L	Yes Yes Yes Yes
3 / 03 Currently In Use	2676	10/1/1997 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH)JKL B DEFOH)JKL	Yes Yes Yes Yes
4 / 04 Currently In Use	2677	10/1/1997 08 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes
5 / 05 Currently In Use	2678	10/1/1997 08 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes
6 / 06 Currently In Use	2679	10/1/1997 08 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes
7 / 07 Currently In Use	4249	10/1/2000 05 / No	Diesel 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH)JKL B DEFOH)JKL	Yes Yes Yes Yes
8 / 08 Currently In Use	4250	10/1/2000 05 / No	Diesel 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B DEFOHIJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 22 of 99

Owner Name and Address: High Altitude Enterprises Inc 544 Rodeo Dr Columbia Falls MT 59912 Phone: (406) 892-3541

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1510895	Glacier Center	10049 US Highway 2 E	Coram	59913	(406) 387-5090	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently in Use	1883	4/17/1988 18 / No	Diesel 6,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
5 / 05 Currently in Use	1884	5/1/1995 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJKL ● ●EFGHIJKL</pre>	Yes Yes Yes Yes
6 / 06 Currently in Use	1885	5/1/1995 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJ&L ● ●EFGHIJ&L</pre>	Yes Yes Yes Yes
7 / 07 Currently in Use	1886	5/1/1995 11 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC • EF G H J K L • • EF G H J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 23 of 99

Owner Name and Address: Jeff Johnson Swiss Chalet Rentals PO Box 190010 Hungry Horse MT 59919 Phone: (406) 387-5504

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1507506	Bobs General Store	8930 US Highway 2 E	Hungry Horse	59919	(406) 387-5504	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4180	9/1/1980 25 / No	Diesel 2,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	4181	9/1/1980 25 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGHIJKU (D) EFGHIJKU	Yes Yes Yes Yes
3 / 03 Currently in Use	4182	9/1/1980 25 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	4183	9/1/1980 25 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 24 of 99

Owner Name and Address: Mikes of Hungry Horse LLC 1645 9th St W Columbia Falls MT 59912 Phone: (406) 387-5271

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1509708	Mikes of Hungry Horse	8820 US Highway 2 E	Hungry Horse	59919	(406) 387-5271	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3239	5/2/1988 18 / No	Gasoline 10,000	STI-P3 None	Bare Steel Cathodically Protected	Pressurized		Yes Yes Yes Yes
2 / 02 Currently in Use	3240	5/2/1988 18 / No	Gasoline 10,000	STI-P3 None	Bare Steel Cathodically Protected	Pressurized	(ABC) EFGHIJKL (D) EFGHIJKL	Yes Yes Yes Yes
3 / 03 Currently in Use	3241	5/2/1988 18 / No	Gasoline 10,000	STI-P3 None	Bare Steel Cathodically Protected	Pressurized	(ABCOEFGH)JKL • • EFGH)JKL	Yes Yes Yes Yes
4 / 04 Currently in Use	3242	5/2/1988 18 / No	Diesel 10,000	STI-P3 None	Bare Steel Cathodically Protected	Pressurized	(ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 25 of 99

Owner Name and Address: Flathead Electric Coop 2510 US Highway 2 E Kalispell MT 59901 Phone: (406) 751-4483

Sys Fac I	Location Name	Location Street Address	Lo	ocation City	Zip	Location Phone
1500044	Flathead Electric Coop Kalispell	2510 US Highway 2 E	Ka	alispell	59901	(406) 752-4483

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently In Use	1090	4/1/1998 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	8 DEF0H1JKL	Yes Yes Yes Yes
5 / 05 Currently In Use	1091	4/1/1998 08 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	B DEFOH1JKL	Yes Yes Yes Yes
6 / 06 Currently In Use	1092	4/1/1998 08 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABC • E F G H J K L B D E F • H J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 26 of 99

Owner Name and Address: Jeffrey S & Kristi Lyn Ruggles 18 Chip Ct Kalispell MT 59901 Phone: (406) 257-0968

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1500108	Evergreen Gas & Deli	2100 US Highway 2 E	Kalispell	59901	(406) 756-7799

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently In Use	3180	6/1/1998 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre></pre>	Yes Yes Yes Yes
5 / 05 Currently In Use	3181	6/1/1998 08 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJK)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Causing	C Inventory Control	- Vapar Manitaring	G Interstit, Dbl-Wall Monitor	SIR	K Deferred
A Manual Tank Gauging	, , , , , , , , , , , , , , , , , , , ,	E Vapor Monitoring			K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed
					· · · · · · · · · · · · · · · · · · ·

Report Generation Date: 7/3/2006 Page 27 of 99

Owner Name and Address: Janelle Gentry 1090 N Meridian Road Kalispell MT 59901 Phone: (406) 755-3750

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1500110	Mini Mikes Market	1090 N Meridian Road	Kalispell	59901	(406) 755-3750

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently In Use	3171	11/1/1997 08 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH))(K) (DEFGH))(K)	Yes Yes Yes Yes
5 / 05 Currently In Use	3172	11/1/1997 08 / No	Diesel 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABCOEFGHUVKU</pre>	Yes Yes Yes Yes
6 / 06 Currently In Use	3173	11/1/1997 08 / No	Gasoline 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 28 of 99

Owner Name and Address: Appleway Conoco 100 N Meridian Road Kalispell MT 59901 Phone: (406) 257-1732

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1500113	Appleway Conoco	100 N Meridian Road	Kalispell	59901	(406) 257-1732

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3141	12/31/1979 26 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(A • • D E F G H J K L E F G H J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	3142	12/31/1979 26 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(A • • DEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
3 / 03 Currently in Use	3143	12/31/1979 26 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(A • • D E F G H J K L • • E F G H J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 29 of 99

Owner Name and Address: Scott Curry PO Box 323 Kalispell MT 59903 Phone: (406) 257-7867

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1500115	Woodland Quikstop	81 Woodland Park Dr	Kalispell	59901	(406) 756-7723

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently In Use	3524	7/23/1998 07 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
4 / 04 Currently In Use	3525	7/23/1998 07 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGH)JKL B (DEFOH)JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed	

Report Generation Date: 7/3/2006 Page 30 of 99

Owner Name and Address: Kalispell Regional Medical Center 310 Sunnyview Ln Kalispell MT 59901 Phone: (406) 751-5775

Sys Fac I	Location Name	Location Street Address	Lo	ocation City	Zip	Location Phone]
1500800	Kalispell Regional Hospital UST	310 Sunnyview Ln	Ka	alispell	59901	 (406) 752-1763	_

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	1465	11/6/1990 15 / No	Other 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	A • C • E F G H J J & L B • E F G H J J & L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 31 of 99

Owner Name and Address: McElroy & Wilken Inc 801 Whitefish Stage Pit 2 PO Box 35 Kalispell MT 59903 Phone: (406) 755-5775

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1501294	McElroy & Wilken Inc Whitefish Stage Pit	801 Whitefish Stage #2	Kalispell	59901	(406) 755-5775

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S6 Currently in Use	1601	12/14/1994 11 / No	Heating Oil 3,000	Fiberglass Reinforced Plastic Double-Walled	Galvanized Steel Double-Walled/Non-Corro	Gravity Feed	ABCDEF.HIJKL B DEF.HIJKL	Yes Yes Yes Yes
2 / 05 Currently in Use	1600	8/1/1994 11 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • EF GH () () () () () () () () () (Yes Yes Yes Yes
3 / 04 Currently in Use	1599	8/1/1994 11 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	(ABC • EF GH) J K L B D E F G H) • K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 32 of 99

Owner Name and Address: Valcon Distributing LTD PO Box 9200 Kalispell MT 59904 Phone: (406) 755-6611

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1501677	Conoco Car Care Center	292 3rd Avenue East N	Kalispell	59901	(406) 755-3797

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 09 Currently in Use	2202	4/23/1986 20 / No	Used Oil 1,000	STI-P3 None	No Piping None	Gravity Feed	<pre>BCDEFGHIJKL B DEFGHIJKL</pre>	Yes Yes Yes Yes
8 / 03 Currently in Use	2201	4/23/1976 30 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	● © E F G H J J K L	Yes Yes Yes Yes
9 / 01 Currently in Use	2199	4/24/1971 35 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
10 / 02 Currently in Use	2200	4/24/1971 35 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABC®EFGH1JKL ® ®EFGH1JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 33 of 99

Owner Name and Address: Valcon Distributing LTD PO Box 9200 Kalispell MT 59904 Phone: (406) 755-6611

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1501680	Valcon Distributing Kalispell	52 5th Avenue West N	Kalispell	59901	(406) 755-6611

TankID/Alt TankID Status		stalled ge/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
9 / 09 Currently In Use		/1998 7 / No	Diesel 25,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL (B DEFOHIJKL)	Yes Yes Yes Yes
10 / 10 Currently In Use		/1998 7 / No	Gasoline 25,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEF 6 H 1 J K L	Yes Yes Yes Yes
11 / 11 Currently In Use		/1998 7 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	8 DEF 6 H 1 J K L	Yes Yes Yes Yes
12 / 12 Currently In Use	3692 11/1/	/1998 7 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	8 DEF 6 H 1 J K L	Yes Yes Yes Yes
13 / 13 Currently In Use		/1998 7 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 34 of 99

Owner Name and Address: G Jerry King 165 River View Dr Kalispell MT 59901 Phone: (406) 756-1030

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1502014	Michael Exxon	1645 US Highway 93 S	Kalispell	59901	(406) 755-4321

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
11 / 11 Currently In Use	650	5/1/1997 09 / No	Diesel 10,000	Composite (Steel w/ FRP) None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H I J K L B D E F • H I J K L	Yes Yes Yes Yes
12 / 12 Currently In Use	651	5/1/1997 09 / No	Diesel 15,000	Composite (Steel w/ FRP) None	Flexible Plastic Double-Walled	Pressurized	B DEF@HIJKU B DEF@HIJKU	Yes Yes Yes Yes
13 / 13 Currently In Use	652	5/1/1997 09 / No	Gasoline 12,000	Composite (Steel w/ FRP) None	Flexible Plastic Double-Walled	Pressurized	ABC • EF G H () () () () () () ()	Yes Yes Yes Yes
14 / 14 Currently In Use	653	5/1/1997 09 / No	Gasoline 15,000	Composite (Steel w/ FRP) None	Flexible Plastic Double-Walled	Pressurized	ABC • EF G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 35 of 99

Owner Name and Address: Sinclair Marketing, Inc 550 E S Temple PO Box 30825 Salt Lake City UT 84130 Phone: (801) 524-2700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1502094	Sinclair Retail 25011	1405 US Highway 2 E	Kalispell	59901	_	-

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Temporarily Out of U		5/1/1994 12 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABC) EFGHIJKL (B) (B) EFGHIJKL	Yes Yes Yes Yes
5 / 05 Temporarily Out of L		5/1/1994 12 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	● ● E F G H J J K L	Yes Yes Yes Yes
6 / 06 Temporarily Out of U		5/4/1994 12 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFGH108L • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 36 of 99

Owner Name and Address: Genesis Developments LLP 3 Meridian Ct 3 Kalispell MT 59901 Phone: (406) 756-7325

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1502330	Michaels Exxon	1011 US Highway 2 W	Kalispell	59901	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
15 / 30 Currently in Use	654	12/1/1992 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
16 / 31 Currently in Use	655	12/1/1992 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKU B DEFOHIJKU	Yes Yes Yes Yes
17 / 32 Currently in Use	656	12/1/1992 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKU B DEFOHIJKU	Yes Yes Yes Yes
18 / 33 Currently in Use	657	4/1/1993 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
19 / 34 Currently in Use	658	4/1/1993 13 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
20 / 35 Currently in Use	659	4/1/1993 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
21 / 36 Currently in Use	660	6/1/1993 13 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 37 of 99

Owner Name and Address: Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1502331	Kum and Go Store 895	1420 1st Ave E	Kalispell	59901	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1303	4/30/1982 24 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFGHIJKL BOEFOHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	1304	4/30/1982 24 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Double-Walled	Pressurized	B	Yes Yes Yes Yes
3 / 03 Currently in Use	1305	4/30/1982 24 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 38 of 99

Owner Name and Address: Montana Diamond Aire Inc 1893 Airport Road Kalispell MT 59901 Phone: (406) 752-5092

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1503172	Diamond Aire Llc Leasee	1893 Airport Road	Kalispell	59901	(406) 752-5092

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
7 / 07 Currently in Use	3285	5/24/1995 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	● DEF●HIJKL	Yes Yes Yes Yes
8 / 08 Currently in Use	3286	5/24/1995 11 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABC (C (F (G (H (1) (K (L (H	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed	

Report Generation Date: 7/3/2006 Page 39 of 99

Owner Name and Address: Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1503915	Kum and Go Store 896	305 E Idaho St	Kalispell	59901	(406) 755-3664

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently In Use	1306	10/1/1998 07 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABC • E F G H 1 J K L) (B D E F • H 1 J K L)	Yes Yes Yes Yes
5 / 05 Currently In Use	1307	10/1/1998 07 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DE F G H J J K L	Yes Yes Yes Yes
6 / 06 Currently In Use	1308	10/1/1998 07 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHUJKL B DEFOHUJKL	Yes Yes Yes Yes
7 / 07 Currently In Use	1309	10/1/1998 07 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 40 of 99

Owner Name and Address: Rocky Mountain Contractors Inc PO Box 8688 Kalispell MT 59904 Phone: (406) 752-4277

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1504359	RMC Kalispell Shop	2214 US Highway 2 E	Kalispell	59901	(406) 752-4280

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	1284	1/1/1994 12 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	ABC●EFGHIJKL B DEFGHI●KL	Yes Yes Yes Yes
4 / 04 Currently in Use	1285	1/1/1994 12 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	ABCOEFGHIJKU B DEFGHIOKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Causing	C Inventory Control	- Vapor Manitoring	G Interstit, Dbl-Wall Monitor	SIR	K Deferred
A Manual Tank Gauging	, , , , , , , , , , , , , , , , , , , ,	E Vapor Monitoring			K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed
					· · · · · · · · · · · · · · · · · · ·

Report Generation Date: 7/3/2006 Page 41 of 99

Owner Name and Address: United Parcel Service 547 S 20th St W Ste 6 Billings MT 59102 Phone: (406) 656-8964

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Ph	one	
1504535	United Parcel Service Kalispell	1151 N Meridian Road	Kalispell	59901	(406) 755-77	95	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	2180	8/1/1993 12 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	8 0 E F 0 H 1 J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 42 of 99

Owner Name and Address: Darryl James Rowe 155 Duff Lane Whitefish MT 59937 Phone: (406) 862-7511

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1504894	Classical Gas Chicken Noodle	343 Main St	Kalispell	59901	(406) 862-7511

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	438	9/14/1995 10 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL OEFGHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	439	9/14/1995 10 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH)JKL (OBEFGH)JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Causing	C Inventory Control	- Vapor Manitoring	G Interstit, Dbl-Wall Monitor	SIR	K Deferred
A Manual Tank Gauging	, , , , , , , , , , , , , , , , , , , ,	E Vapor Monitoring			K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed
					· · · · · · · · · · · · · · · · · · ·

Report Generation Date: 7/3/2006 Page 43 of 99

Owner Name and Address: Cenex Supply & Marketing PO Box 579 Kalispell MT 59903 Phone: (406) 755-9425

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1505069	Equity Supply Convenience Store	120 W Idaho St	Kalispell	59901	(406) 755-7489	_

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 13 Currently in Use	868	3/1/1996 10 / No	Diesel 15,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC0E0GH1JKL B 0EF0H1JKL	Yes Yes Yes Yes
2 / 11 Currently in Use	866	3/1/1996 10 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	B 0 E F 0 H 1 J K L	Yes Yes Yes Yes
3 / 12 Currently in Use	867	3/1/1996 10 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABC • E • G H 1 J K L B • E F • H 1 J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 44 of 99

Owner Name and Address: Evans Farms 295 Middle Road Kalispell MT 59901 Phone: (406) 257-2021

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1505344	Evans Farms	295 Middle Road	Kalispell	59901		

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S4 Currently in Use	870	11/1/1995 10 / No	Diesel 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	B C D E F G H J J K LB D E F G H J ● K L	Yes Yes Yes Yes
2 / S3 Currently in Use	869	11/1/1995 10 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<pre>BCDEFGHJ&L B DEFGHJ®KL</pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 45 of 99

Owner Name and Address: Woodys Country Store Inc 3333 MT Highway 35 Kalispell MT 59901 Phone: (406) 755-5544

Sys Fac I	Location Name	Location Street Address		Location City	Zip	Location Phone	I
1505801	Woodys Country Store Inc	3333 MT Highway 35	Ī	Kalispell	59901	(406) 755-5544	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	2243	12/5/1984 21 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Impressed Current	Pressurized	ABC ●EFGH1JKL ● ●EFGH1JKL	Yes Yes Yes Yes
2 / 02 Currently in Use	2244	12/5/1984 21 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Impressed Current	Pressurized	● B C ● E F G H ()	Yes Yes Yes Yes
3 / 03 Currently in Use	2245	12/5/1984 21 / No	Diesel 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Impressed Current	Pressurized	ABCOEFGHIJKL O OEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 46 of 99

Owner Name and Address: Tab Young & Marcie Riley 25 Batavia Ln Kalispell MT 59901 Phone: (406) 752-5880

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1506101	Kelly Raes Inc	25 Batavia Ln	Kalispell	59901	(406) 752-5880

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 03 Currently in Use	4505	2/1/1994 12 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	A • • D E F G H I J K L • • E F G H I J K L	Yes Yes Yes Yes
4 / S5 Currently in Use	4506	1/1/1965 41 / Ye	Gasoline 10,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEFGH)J(L) (D) (D) (E) (G) (H) (J(L))	Yes Yes Yes Yes
5 / S4 Currently in Use	4507	1/1/1965 41 / Ye	Gasoline 8,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEFGH)J&L (BCBFGH)J&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 47 of 99

Owner Name and Address: Flathead County Commissioners 800 S Main St Kalispell MT 59901 Phone: (406) 758-5790

Sys Fac I	Location Name	Location Street Address	Location City	/ Zip	Location Phone	
1506286	Flathead County Road Dept	1249 Willow Glen Dr	Kalispell	59901	(406) 758-5790	-

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
8 / 08 Currently In Use	1088	5/1/1998 08 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
9 / 09 Currently In Use	1089	5/1/1998 08 / No	Gasoline 3,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 48 of 99

Owner Name and Address: MGS Partners Oles 10 PO Box 3356 Missoula MT 59806 Phone: (406) 728-8646

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1507432	Oles Country Store 10	2490 US Highway 93 N	Kalispell	59901	(406) 752-4970

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	382	4/23/1985 21 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	383	4/23/1985 21 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes
3 / 03 Currently In Use	4685	6/21/2002 04 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 49 of 99

Owner Name and Address: Robert E Harris 2604 US Highway 2 E Kalispell MT 59901 Phone: (406) 752-4884

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1507490	Tri City Quick Stop	2604 US Highway 2 E	Kalispell	59901	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 08 Currently in Use	1289	4/1/1995 11 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H I J K L B D E F • H I J K L	Yes Yes Yes Yes
6 / 05 Currently in Use	4414	4/1/1995 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEF GH J J K L	Yes Yes Yes Yes
7 / 06 Currently in Use	1287	4/1/1995 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC • EF G H () () () () () () ()	Yes Yes Yes Yes
8 / 07 Currently in Use	1288	4/1/1995 11 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABC • EF GH) J K L B D E F • H) J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 50 of 99

Owner Name and Address: Lanes Enterprises LLC 903 Conrad Drive Kalispell MT 59901 Phone: (406) 756-0399

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1508357	Lanes Food and Fuel	1454 US Highway 2 E	Kalispell	59901	(406) 752-4962

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	1420	5/8/1982 24 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	(ABCOEFGHIJKL • • EFGH• JKL	Yes Yes Yes Yes
2 / 02 Currently in Use	1421	5/8/1982 24 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	(ABCOEFGHOJKL • • EFGHOJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed	

Report Generation Date: 7/3/2006 Page 51 of 99

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1508709	Town Pump Inc Kalispell 1	445 W Idaho St	Kalispell	59901	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4679	4/14/1982 24 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<pre>A • • • E F G H] J K L B • E F G H] J K L</pre>	Yes Yes Yes Yes
2 / 02 Currently in Use	2425	4/14/1982 24 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	B	Yes Yes Yes Yes
6 / 06 Currently In Use	2426	5/28/1997 09 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHUJKL B OEFGHUJKL	Yes Yes Yes Yes
7 / 07 Currently In Use	4680	5/28/1997 09 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	\(\begin{align*} ali	Yes Yes Yes Yes
8 / 08 Currently In Use	4939	8/18/2004 01 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFOHUJKL • • EFGHUJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 52 of 99

Owner Name and Address: Montana Department of Deadhead Helena MT 59620 Phone: (406) 444-6200

Transportation

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1508733	MDOT Kalispell	85 5th Avenue East N	Kalispell	59901	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 04 Currently in Use	2892	12/1/1991 14 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	(ABCD®FGH)JKL (BD®FGH)JKL	Yes Yes Yes Yes
4 / 05 Currently in Use	2893	12/1/1991 14 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	(ABCD®FGH)JKL (B D®FGH)JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 53 of 99

Owner Name and Address: Flathead County Commissioners 800 S Main St Kalispell MT 59901 Phone: (406) 758-5790

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1509279	Flathead County Justice Center	920 S Main St	Kalispell	59901	(406) 758-5561

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3810	3/11/1987 19 / No	Diesel 6,000	STI-P3 None	No Piping None	Safe Suction	B DEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 54 of 99

Owner Name and Address: Grosswiler Dairy PO Box 952 Kalispell MT 59903 Phone: (406) 755-2371

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1509329	Grosswiler Dairy W Valley Dr	1665 W Valley Dr	Kalispell	59901	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 06 Temporarily Out of Use		2/12/1974 32 / No	Gasoline 1,200	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEFGHIJK® B DEFGHIJK®	No No No No
2 / 07 Temporarily Out of Use		2/12/1974 32 / No	Diesel 1,200	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	B DEFGHIJK •	No No No No
3 / S4 Temporarily Out of Use		2/12/1974 32 / No	Heating Oil 1,200	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEFGHIJK• B DEFGHIJK•	No No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 55 of 99

Owner Name and Address: Cenex Supply & Marketing PO Box 579 Kalispell MT 59903 Phone: (406) 755-9425

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1509705	Cenex Harvest States Kalispell	55 4th Avenue East N	Kalispell	59901	(406) 755-5977

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3786 3/26/1981 25 / No	Diesel 20,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	A • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes
2 / 02 Currently in Use	3787 3/26/1981 25 / No	Gasoline 20,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<pre></pre>	Yes Yes Yes Yes
3 / 03 Currently in Use	3788 3/26/1981 25 / No	Diesel 20,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<pre>A • • D E F G H] J & L • • E F G H] J & L</pre>	Yes Yes Yes Yes
8 / 08 Currently In Use	4075 3/1/1999 07 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC●EF®H ① & Û B ●EF®H ① & Û	Yes Yes Yes Yes
9 / 09 Currently In Use	4076 3/1/1999 07 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 56 of 99

Owner Name and Address: Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1509707	Holiday Stationstore 279	1278 US Highway 2 E	Kalispell	59901	(406) 752-6299	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3005	6/1/1985 21 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Impressed Current	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	3006	6/1/1985 21 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Impressed Current	Pressurized		Yes Yes Yes Yes
3 / 03 Currently in Use	3007	6/1/1985 21 / No	Gasoline 10,000	STI-P3 None	Galvanized Steel Impressed Current	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	3008	6/1/1985 21 / No	Diesel 10,000	STI-P3 None	Galvanized Steel Impressed Current	Pressurized	(ABCOEFGHIJKL) (DEFGHIJKL)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 57 of 99

Owner Name and Address: Darryl Bjork 1319 US Highway 93 S Kalispell MT 59901 Phone: (406) 752-7339

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1509820	Mulligans Conoco	1319 US Highway 93 S	Kalispell	59901	(406) 752-7339	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 05 Currently in Use	1847	9/1/1995 10 / No	Diesel 15,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>A • C • E F G H J & L • • E F G H J & L </pre>	Yes Yes Yes Yes
2 / 06 Currently in Use	1848	9/1/1995 10 / No	Gasoline 15,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre></pre>	Yes Yes Yes Yes
3 / 07 Currently in Use	1849	9/1/1995 10 / No	Gasoline 7,500	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(A • C • E F G H 1 J K L • • E F G H 1 J K L	Yes Yes Yes Yes
4 / 08 Currently in Use	1850	9/1/1995 10 / No	Diesel 7,500	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>A • C • E F G H 1 J K L • • E F G H 1 J K L </pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 58 of 99

Owner Name and Address: West Valley School Dist 1 2290 Farm To Market Road Kalispell MT 59901 Phone: (406) 755-7239

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1510295	West Valley School Dist 1	2290 Farm To Market Road	 Kalispell	59901	_	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / S2 Currently in Use	2249 8/9/1995 10 / No	Heating Oil 1,000	Fiberglass Reinforced Plastic None	Copper Double-Walled/Non-Corro	Safe Suction	<pre>BCDEFGHIJKU B DEFOHIOKU</pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 59 of 99

Owner Name and Address: Red Eagle Aviation Inc 1880 US Highway 93 S PO Box 166 Kalispell MT 59903 Phone: (406) 755-2376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1511166	Red Eagle Aviation Inc	1880 US Highway 93 S	Kalispell	59901	(406) 755-2376

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 04 Currently In Use	4173	1/1/1981 25 / No	Other 12,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
3 / 03 Currently In Use	4144	1/1/1981 25 / No	Other 12,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL (D) (D) (B) (D) (D) (D) (D) (D) (D) (D) (D) (D) (D	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 60 of 99

Owner Name and Address: City Service Inc PO Box 1 Kalispell MT 59903 Phone: (406) 755-4321

Sys Fac ILocation NameLocation Street AddressLocation CityZipLocation Phone1512435Rental Car BuildingKalispell59901

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	665 5	5/17/1991 15 / No	Gasoline 6,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Safe Suction	ABC⊕EFGHJ& B DEFGHJ&	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 61 of 99

Owner Name and Address: White Oak of Montana LLC 4810 US Highway 93 S Kalispell MT 59901 Phone: (406) 857-2344

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1513287	White Oak Market Inc	4810 US Highway 93 S	Kalispell	59901	(406) 857-2344	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4481	10/1/1983 22 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	ABC●EFGHIJ&L B DEF●HIJ&L	Yes Yes Yes Yes
2 / 02 Currently in Use	4482	11/1/1983 22 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHUUKL B DEFOHUUKL	Yes Yes Yes Yes
3 / 03 Currently in Use	4483	11/1/1983 22 / No	Diesel 6,000	Asphalt Coated or Bare Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	ABC•EFGH108L B DEF•H108L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 62 of 99

Owner Name and Address: DJL LLC 2075 Highway 2 E Kalispell MT 59901 Phone: (406) 755-7447

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1513730	Brians C Store	2075 US Highway 2 E	Kalispell	59901	(406) 755-7447

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 02 Currently in Use	3353	6/1/1996 10 / No	Gasoline 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
2 / 03 Currently in Use	3354	6/1/1996 10 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes
3 / 06 Currently in Use	3357	6/1/1996 10 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	3355	6/1/1996 10 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL	Yes Yes Yes Yes
5 / 05 Currently in Use	3356	6/1/1996 10 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL	Yes Yes Yes Yes
6 / 01 Currently in Use	3352	6/1/1996 10 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 63 of 99

Owner Name and Address: Phin LLC 3 Meridian Ct Ste 3 Kalispell MT 59901 Phone: (406) 755-4321

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1513732	Town Pump Inc Kalispell 3	2605 US Highway 2 E	Kalispell	59901	(406) 755-1306	•

TankID/Alt TankID Status	Tag Installed Age/AST		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4766 7/1/1996 10 / N	Gasoline 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABC ● E F G H () (K L) (B D E F G H () ● (K L)	Yes Yes Yes Yes
2 / 02 Currently in Use	4767 7/1/1996 10 / N	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEFGHIJKL B DEFGHI	Yes Yes Yes Yes
3 / 03	4768 7/1/1996	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	ABC@EFGHIJKL	Yes
Currently in Use	10 / N	15,000	None	Double-Walled		B DEFGHI®KL	Yes Yes Yes
4 / 04	4769 7/1/1996	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	ABCOEFGHIJKL	Yes
Currently in Use	10 / N	8,000	None	Double-Walled		B DEFOHIOKL	Yes Yes Yes
5 / 05	4770 7/1/1996	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	ABCOEFGHIJKL	Yes
Currently in Use	10 / N	8,000	None	Double-Walled		B DEFOHIOKL	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 64 of 99

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1513764	Town Pump Inc Kalispell 2	1100 E Idaho St	Kalispell	59901	<u> </u>

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4814	4/1/1997 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	4815	4/1/1997 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized		Yes Yes Yes Yes
3 / 03 Currently in Use	4816	4/1/1997 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHOJ&U B DEFOHOJ&U	Yes Yes Yes Yes
4 / 04 Currently in Use	4817	4/1/1997 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKU B DEFOHIJKU	Yes Yes Yes Yes
5 / 05 Currently in Use	4818	4/1/1997 09 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHOJKU B DEFOHOJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 65 of 99

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1513765	Town Pump Inc Kalispell 5	2910 US Highway 93 S	Kalispell	59901	(406) 257-1419	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3430	9/1/1996 09 / No	Diesel 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B 0 E F 0 I J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	3431	9/1/1996 09 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B 0 E F 0 H 1 J K L	Yes Yes Yes Yes
3 / 03 Currently in Use	3432	9/1/1996 09 / No	Gasoline 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC ● EFGH1JKL B ●EF●H1JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 66 of 99

Owner Name and Address: City Service Inc PO Box 1 Kalispell MT 59903 Phone: (406) 755-4321

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613824	City Service Bulk Plant	1841 3rd Ave E	Kalispell	59901	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	681	8/1/1997 08 / No	Diesel 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKU B DEFOHIJKU	Yes Yes Yes Yes
2 / 02 Currently In Use	682	8/1/1997 08 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGH)J&U B (DEFOH)J&U	Yes Yes Yes Yes
3 / 03 Currently In Use	683	8/1/1997 08 / No	Gasoline 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJ&U B DEFOHIJ&U	Yes Yes Yes Yes
4 / 04 Currently In Use	684	8/1/1997 08 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKU B DEFOHIJKU	Yes Yes Yes Yes
5 / 05 Currently In Use	685	8/1/1997 08 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGH)JKL B (DEFOH)JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 67 of 99

Owner Name and Address: New Albertsons Inc PO Box 20 Boise ID 83726 Phone: (208) 395-6200

Sys Fac I	Location Name	Location Street Address		Location City	Zip	Location Phone
5613985	Albertsons Express 2018	900 W Idaho St		Kalispell	59901	(406) 257-7127

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4239	10/1/2000 05 / No	Gasoline 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABC • E F • H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently In Use	4240	10/1/2000 05 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 68 of 99

Owner Name and Address: Eagle Fuels LLC 1079 Hodgson Road Columbia Falls MT 59912 Phone: (406) 862-5422

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614014	Eagle Fuels LLC	3150 US Highway 2	Kalispell	59901	(406) 862-5422

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4605	7/1/2001 05 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently In Use	4606	7/1/2001 05 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEF 6 H 1 J & L	Yes Yes Yes Yes
3 / 03 Currently In Use	4607	7/1/2001 05 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJ&U B DEFOHIJ&U	Yes Yes Yes Yes
4 / 04 Currently In Use	4608	7/1/2001 05 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKU B DEFOHIJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 69 of 99

Owner Name and Address: Flathead County Commissioners 800 S Main St Kalispell MT 59901 Phone: (406) 758-5790

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614041	Flathead County Solid Waste Dist	4098 US Highway 93 N	Kalispell	59901	(406) 758-5918

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4559	11/26/2001 04 / No	Used Oil 1,000	Fiberglass Reinforced Plastic Double-Walled	No Piping None	Not Listed	8 DEFGHIJKL	No Yes Yes Yes
2 / S2 Currently In Use	4802	2/25/2003 03 / Ye	Diesel 15,000	Concrete None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGH10.L B DEF.H10.KL	No Yes Yes Yes
3 / S3 Currently In Use	4803	2/25/2003 03 / No	Gasoline 3,000	Concrete None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGH108L B DEF•H108L	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 70 of 99

Owner Name and Address: Smiths Food and Drug 1540 S Redwood Road Salt Lake City UT 84104 Phone: (801) 977-1048

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5614062	Smiths Fuel Center 172	195 3rd Avenue West N	Kalispell	59901	(406) 752-5705	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4742	8/23/2002 03 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B 0 E E H J K L	Yes Yes Yes Yes
2 / 02 Currently In Use	4743	8/23/2002 03 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B	Yes Yes Yes Yes
3 / 03 Currently In Use	4744	8/23/2002 03 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABC®EF®HIJ&L B ®EF@HIJ&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 71 of 99

Owner Name and Address: Flathead Surgical and Diagnostic 310 Sunnyview Ln Kalispell MT 59901 Phone: (406) 752-5111

Cente

Sys Fac ILocation NameLocation Street AddressLocation CityZipLocation Phone5614072Flathead Surgical and Diagnostic Center310 Sunnyview LnKalispell59901(406) 756-3695

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently In Use	4880 1	12/16/2003 02 / Ye	Diesel 6,000	Concrete Double-Walled	Flexible Plastic Double-Walled	Pressurized	B DEF®HIJ&L	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 72 of 99

Owner Name and Address: Costco Wholesale 67 999 Lake Dr Issaquah WA 98027 Phone: (425) 427-7696

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
6015012	Costco Wholesale	2330 Highway 93N	Kalispell	59901	(406) 758-2500

TankiD/Alt TankiD Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	5033	10/7/2005 00 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKU B OEFOHIJKU	Yes Yes Yes Yes
2 / 02 Currently in Use	5034	10/7/2005 00 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized		Yes Yes Yes Yes
3 / 03 Currently in Use	5035	10/7/2005 00 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 73 of 99

Owner Name and Address: Federal Aviation Administration 2150 W 700 N Salt Lake City UT 84116 Phone: (406) 549-8300

Sys Fac I	Location Name	Location Street Address	Locat	ion City	Zip	I	Location Phone	
1503618	ARSR GATR Bldg	Blacktail Mountain Road	Lakes	ide	59922		(406) 755-5499	•

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / S5	4565 9/25/1996	Diesel	Unknown	Flexible Plastic	Pressurized	ABCDEFGHJ.L	Yes
Currently In Use	09 / Ye	2,000	None	Double-Walled		B DEF.HJ.KL	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 74 of 99

Owner Name and Address: Robert Lincoln Land LLC 282 N Juniper Bay Road Somers MT 59932 Phone: (406) 857-3139

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1510513	Joe Blogz	7170 US Highway 93 S	Lakeside	59922	(406) 844-3372

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3798	3/7/1985 21 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	(ABC●EFGH1)&L B DEF●H1)&L	Yes Yes Yes Yes
2 / 02 Currently in Use	3799	3/7/1985 21 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKU B DEFOHIJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed	

Report Generation Date: 7/3/2006 Page 75 of 99

Owner Name and Address: Steven & Janet Heinze PO Box 215 Lakeside MT 59922 Phone: (406) 844-0123

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1513487	Lakeside City Market Inc	7254 US Highway 93 S	Lakeside	59922	(406) 844-0123

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 04 Currently in Use	669	8/1/1994 11 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL) (BCOEFGHIJKL)	Yes Yes Yes Yes
2 / 02 Currently in Use	667	8/1/1994 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
3 / 03 Currently in Use	668	8/1/1994 11 / No	Diesel 7,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(A B C • E F G H) J (K L) • • E F G H) J (K L)	Yes Yes Yes Yes
4 / 01 Currently in Use	666	8/1/1994 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH)J&L (OBFGH)J&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 76 of 99

Owner Name and Address: Van Kirke Nelson PO Box 1175 Kalispell MT 59903 Phone: (406) 755-5656

Sys Fac I	Location Name	Location Street Address	Location City Zig	Location Phone	
5614069	Dr Van Kirke Nelson	616 Lutheran Camp Road		922 (406) 752-5252	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently In Use	4781	12/30/2002 03 / No	Heating Oil 800	Composite (Steel w/ FRP) None	Flexible Plastic Double-Walled	U.S. Suction	● B C D E F G H 1 J K L 	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 77 of 99

Owner Name and Address: Vern Taber Moose Crossing Inc 8405 US Highway 2 W Marion MT 59925 Phone: (406) 854-2070

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1510015	Moose Crossing Inc	8405 US Highway 2 W	Marion	59925	(406) 854-2070	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / S3 Currently In Use	1245	9/25/1997 08 / Ye	Gasoline 4,000	Unknown None	Flexible Plastic Double-Walled	Gravity Feed	ABCDEFGHIJEL B DEFOHIJEL	Yes Yes Yes Yes
4 / S4 Currently In Use	1246	9/25/1997 08 / Ye	Gasoline 3,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	B DEF@HIJ&L B DEF@HIJ&L	Yes Yes Yes Yes
5 / S5 Currently In Use	1247	9/25/1997 08 / Ye	Diesel 1,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGHIJ&L) B (DEFOHIJ&L)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 78 of 99

Owner Name and Address: Terrance G Sidener 8205 US Highway 2 W Marion MT 59925 Phone: (406) 854-2552

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5613803	HillTop Quick Stop	8205 US Highway 2 W	Marion	59925	(406) 854-2442	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Temporarily Out of U		8/1/1997 08 / No	Gasoline 5,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
2 / 02 Temporarily Out of L		8/1/1997 08 / No	Gasoline 5,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
3 / 03 Temporarily Out of U		8/1/1997 08 / No	Diesel 5,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 79 of 99

Owner Name and Address: Cabin Creek Landing LLC 2820 Helena Flats Road Kalispell MT 59901 Phone: (406) 752-0051

l	Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
	5614102	Cabin Creek Landing LLC	166 Wright Way	Marion	59925		

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4883	2/9/2004 02 / No	Other 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC@EF@HIJKU B DEF@HIJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 80 of 99

Owner Name and Address: Glacier Gold LLC PO Box 260 Olney MT 59927 Phone: (406) 881-3033

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1502973	Glacier Gold LLC	255 Good Creek Road	Olney	59927	(406) 881-3033

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 03 Temporarily Out of U		3/29/1988 18 / No	Gasoline 9,000	STI-P3 None	No Piping None	Pressurized	ABCOEFGHIJKL B DEFGHIJKL	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed	

Report Generation Date: 7/3/2006 Page 81 of 99

Owner Name and Address: Donna & Reggie Briggs PO Box 162 Olney MT 59927 Phone: (406) 881-2692

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613849	Briggs Mercantile	105 Olney Loop Road	Olney	59927	(406) 881-2692

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently In Use	3504	6/1/1998 08 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • E F G H J K L B D E F G H • K L	Yes Yes Yes Yes
4 / 04 Currently In Use	3505	6/1/1998 08 / No	Gasoline 500	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABCOEFGH)JKL (B DEFGH)OKL	Yes Yes Yes Yes
5 / 05 Currently In Use	3506	6/1/1998 08 / No	Diesel 500	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • E F G H J K L B D E F G H • K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 82 of 99

Owner Name and Address: US Department of Interior Glacier National Park PO Box 128 West Glacier MT 59936 Phone: (406) 888-7870

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1502743	Polebridge Ranger Station	Polebridge Ln	Polebridge	59928	(406) 888-7978

TankID/Alt TankID Status	Tag Installed Numbe Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	1218 6/1/1990 16 / No	Gasoline 2,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	(ABCDEF.H)J.K.L (B. OEFOH)J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 83 of 99

Owner Name and Address: Points North Trading Co 87867 Highway 93 PO Box 1 Rollins MT 59931 Phone: (406) 844-3942

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2412730	Points North Trading Co	87867 US Highway 93	Rollins	59931	· <u></u>

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 03 Currently in Use	3095	6/1/1995 11 / No	Gasoline 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	\(\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Yes Yes Yes Yes
2 / 04 Currently in Use	3096	6/1/1995 11 / No	Gasoline 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGH() (R)	Yes Yes Yes Yes
3 / 05 Currently in Use	3097	6/1/1995 11 / No	Diesel 4,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 84 of 99

Owner Name and Address: West Glacier Mercantile Inc 200 Going To The Sun Road PO Box 410 West Glacier MT 59936 Phone: (403) 888-5

Sys Fac I	Location Name	Location Street Address		Location City	Zip	<u> </u>	Location Phone	
1503288	West Glacier Mercantile Inc	200 Going To The Sun Road	_	West Glacier	59936	-		

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently in Use	2246	10/23/1989 16 / No	Gasoline 10,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFOHIJKL O DEFGHIOKL	Yes Yes Yes Yes
5 / 05 Currently in Use	2247	10/23/1989 16 / No	Gasoline 8,000	STI-P3 Double-Walled	No Piping None	Pressurized	(ABCOEFOH) JKL B DEFGH) JKL	Yes Yes Yes Yes
6 / 06 Currently in Use	2248	10/23/1989 16 / No	Gasoline 6,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFOHIJKL • • EFGHI•KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 85 of 99

Owner Name and Address: US Department of Interior Glacier National Park PO Box 128 West Glacier MT 59936 Phone: (406) 888-7870

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1509491	Glacier Park Hdqtrs Gas Pumps	128	West Glacier	59936	(406) 888-7978

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 06 Currently in Use	1219	11/1/1990 15 / No	Diesel 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Not Listed	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes
6 / 07 Currently in Use	1220	11/1/1990 15 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Not Listed	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 86 of 99

Owner Name and Address: Glacier Highland Resort PO Box 397 West Glacier MT 59936 Phone: (406) 888-5427

Sys Fac I	Location Name	Location Street Address		Location City	Zip	Location Phone
1510685	Glacier Highland Resort	US 12555 Highway 2 E	_	West Glacier	59936	(406) 888-5427

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently In Use	3214	10/1/1998 07 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABC • E F G H 1 J K L • • E F G H 1 J K L	Yes Yes Yes Yes
4 / 04 Currently In Use	3215	10/1/1998 07 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC●EFGH1JKL ● ●EFGH1JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 87 of 99

Owner Name and Address: Barnes Enterprises Inc PO Box 4269 Whitefish MT 59937 Phone: (406) 862-4535

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1500112	Westside Exxon	145 2nd St W	Whitefish	59937	(406) 862-4556	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	3421	11/1/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	3422	11/1/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJK) B (DEFOHIJK)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 88 of 99

Owner Name and Address: MT Dept of Natural Resources & 2250 US Highway 93 N Kalispell MT 59901 Phone: (406) 881-2371

Conservation

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1503598	MT DNRC Whitefish	7425 US Highway 93 N	Whitefish	59937	(406) 881-2371

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 04 Currently in Use	1671	7/1/1992 14 / No	Gasoline 1,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEF.H.J.K.L B DEF.G.H.J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 89 of 99

Owner Name and Address: Stacey Oil Co 243 Spokane Ave Whitefish MT 59937 Phone: (406) 862-2777

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1504428	Stacey Oil Co	243 Spokane Ave	Whitefish	59937	(406) 862-2777	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
8 / S9 Currently in Use	1966	10/21/1991 14 / No	Used Oil 500	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	● B C D E F G H I J K LB D E F G H I ● K L	Yes Yes Yes Yes
10 / 10 Currently in Use	1961	10/21/1991 14 / No	Diesel 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	B DEFGHIJKL B DEFGHIJKL	Yes Yes Yes Yes
11 / 11 Currently in Use	1962	10/21/1991 14 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EF@H]J&L ● ●EF@H]J&L</pre>	Yes Yes Yes Yes
12 / 12 Currently in Use	1963	10/21/1991 14 / No	Diesel 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
13 / 14 Currently in Use	1964	4/1/1992 14 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes
14 / 15 Currently in Use	1965	4/1/1992 14 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006

Owner Name and Address: Mikes of Whitefish Inc 1656 9th St W Columbia Falls MT 59912 Phone: (406) 892-2078

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1504903	Mikes Conoco Whitefish	6585 US Highway 93 S	Whitefish	59937	(406) 862-6453

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
7 / 07 Currently in Use	2956	11/4/1991 14 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL (OBCOEFGHIJKL)	Yes Yes Yes Yes
8 / 08 Currently in Use	2957	11/4/1991 14 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGH (J) (K) (L) (L) (L) (L) (L) (L) (L) (L) (L) (L	Yes Yes Yes Yes
9 / 09 Currently in Use	2958	11/4/1991 14 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
10 / 10 Currently in Use	2959	11/4/1991 14 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 91 of 99

Owner Name and Address: Winter Sports Inc PO Box 1400 Whitefish MT 59937 Phone: (406) 862-2987

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1505579	Big Mountain Ski Resort Shop	3910 Big Mountain Road	Whitefish	59937	(406) 862-1900	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
8 / 08 Currently in Use	2295	9/1/1992 13 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL (BCOEFGHIJKL	Yes Yes Yes Yes
9 / 09 Currently In Use	2296	7/14/1998 07 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Safe Suction	B DEFGHIOKL B DEFGHIOKL	Yes Yes Yes Yes
10 / 10 Currently In Use	2297	7/14/1998 07 / No	Diesel 2,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Safe Suction	ABC●EFGH() & L B DEFGH() ● & L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 92 of 99

Owner Name and Address: Dan Scheffer 4899 US Highway 93 S Whitefish MT 59937 Phone: (406) 862-6365

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1507766	Midway Mini Mart	4899 US Highway 93 S	Whitefish	59937	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently in Use	3384	4/1/1996 10 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKU • • EFGHIJKU	Yes Yes Yes Yes
5 / 05 Currently in Use	3385	4/1/1996 10 / No	Gasoline 7,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH)JKU (DEFGH)JKU	Yes Yes Yes Yes
6 / 06 Currently in Use	3386	4/1/1996 10 / No	Diesel 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH)JKL (O) (E) (F) (H) (J) (K) (L)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 93 of 99

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1510105	Town Pump Inc Whitefish 2	6600 US Highway 93 S	Whitefish	59937	(406) 862-7204

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	2428	1/17/1990 16 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHJJKL B OEFGHJJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	4306	1/17/1990 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	B	Yes Yes Yes Yes
3 / 03 Currently in Use	2430	1/17/1990 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC●EFGHJ&L B ●EFGHJJ&L	Yes Yes Yes Yes
4 / 04 Currently in Use	2431	1/17/1990 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC●EFGHJ&L B ●EFGHJJ&L	Yes Yes Yes Yes
5 / 05 Currently in Use	4941	10/1/2004 01 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFOHJUKU B OEFGHJUKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 94 of 99

Owner Name and Address: Triangle R Corp 721 Wisconsin Ave Whitefish MT 59937 Phone: (406) 862-5025

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1510944	Alpine Village Market	721 Wisconsin Ave	Whitefish	59937	(406) 862-5025

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4692	4/21/1981 25 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	4693	4/21/1981 25 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Double-Walled	Pressurized	8 DEF 6 H 1 J K L	Yes Yes Yes Yes
3 / 03 Currently in Use	4694	10/1/1991 14 / No	Diesel 5,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 95 of 99

Owner Name and Address: Whitefish Lake Lodge 1399 Wisconsin Ave PO Box 2040 Whitefish MT 59937 Phone: (406) 837-7050

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1512719	Whitefish Lake Lodge	1396 Wisconsin Ave	Whitefish	59937	(406) 862-2929

TankID/Alt TankID Status	· ·	stalled je/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	4898 4/1/1:		Gasoline 4,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCDEF.H.I.J.K.L.	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 96 of 99

Owner Name and Address: North Valley Hospital 6575 US Highway 93 S Whitefish MT 59937 Phone: (406) 863-3500

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1513571	North Valley Hospital US 93 S	6575 US Highway 93 S	Whitefish	59937	(406) 863-2501

TankID/Alt TankID Status	Tag Installed Numbe Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01	3235 9/1/1987	Diesel	STI-P3	Flexible Plastic	Gravity Feed	ABCOEFGHIJKL	Yes
Currently in Use	18 / No	3,500	None	Double-Walled		B DEFOHIOKL	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 97 of 99

Owner Name and Address: David L Nichols PO Box 36 Whitefish MT 59937 Phone: (406) 862-4992

Sys Fac I	Location Name	Location Street Address	Locat	ion City	Zip	Location Phone]
5613938	Nichols Residence	7277 Farm to Market Road	White	fish	59937	(406) 862-4992	•

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently In Use	4070	6/1/1999 07 / No	Gasoline 1,000	Fiberglass Reinforced Plastic None	Galvanized Steel Cathodically Protected	Safe Suction	8 DEFGH10KL	Yes Yes Yes Yes
2 / S2 Currently In Use	4071	6/1/1999 07 / No	Diesel 1,000	Fiberglass Reinforced Plastic None	Galvanized Steel Cathodically Protected	Safe Suction	8 DEFGH1061	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 98 of 99

Owner Name and Address: City of Whitefish PO Box 158 Whitefish MT 59937 Phone: (406) 863-2460

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5614145	Whitefish School Dist Central School	600 2nd St E	Whitefish	59937	(406) 862-8640	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	0	/ No	Not Listed 1,100	Not Listed None	Not Listed None	Not Listed	ABCDEFGHIJKO B DEFGHIJKO	No No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 99 of 99